

Ecological Modeling at the Landscape Scale




US Army Corps
of Engineers

Wetland and Coastal Ecology Branch

Engineer Research and Development Center

MAWI – Multi-scale Assessment of Watershed Integrity

- **Goal: Provide a suite of tools that can be used to...**




MAWI


- ◆ **Multi-scale Assessment of Watershed Integrity (MAWI)**
 - ❖ **Spatial Decision Support System**
 - ❖ **Uses multiple scales, assesses multiple disciplines**
 - ❖ **Involves field sampling**
 - ❖ **Serves as a baseline assessment and focusing tool**
 - ❖ **Has previously been applied throughout California, being developed for western New York and Indiana**



Kleiss S. 00

Baseline Watershed Assessment Tasks





Zone 1: “V” Shaped Valleys

Zone 2: Colluvial Valleys

Zone 3: Boulder Dominated Floodplain/Terrace Complexes

Zone 4: Small Alluvial Valleys


Zone 5: Large Alluvial Valleys

◆ Geomorphic zone assignment



◆ Critical to restoration planning



**US Army Corps
of Engineers**



Engineer Research and Development Center



◆ Assessment Units

- ◆ Stream reaches
- ◆ Local Drainages
- ◆ Drainage Area



US Army Corps
of Engineers

Watershed Assessment – Reach Evaluation

- Field work at the riparian reach scale included:
 - Assessing reach scale indicators
 - Characterizing the riparian reach in representative locations in terms of:
 - Stream type, geometry, and substrate
 - Dominant vegetation
 - Sediment regime
 - Cultural alteration
 - Other factors
- This information was utilized to develop riparian reach restoration templates

Riparian Reach Characterization Form – San Diego Creek

Field Notes and Comments

Reach Identifier: AC6 Aerial Photo Line / No: 729

Date: 8/2 / 1999 Field Crew: RDS

UTM Coord. Downstream End 11S: 435041 mE: 3727264 mN

UTM Coord. Upstream End 11S: 435661 mE: 3727833 mN

7.5 Minute Quad Name: E1 T200 T: R: S: Q:

Reach Drainage Basin Area: 6.6 4a

Valley Type: I II III IV V VI VII VIII IX X XI

Valley Slope: 7 % Valley Width: 220 m ft Reach Length: 260 m ft

Stream Type: Aa+ A B C D Da E F G 1 2 3 4 5 6

Channel Slope: 6 % Sinuosity: 1.2 (valley slope / channel slope)

BKF Width (Wbkt): 8 m / ft Floodplain Width (Wfpa): 10 m / ft

BKF Max Depth (dmax): 30 m / ft BKF Mean Depth (dbkf): 24 m / ft

Width / Depth Ratio: Wbkt 4 (Wbkt / dbkf) Entrench Ratio: 1.25 (Wfpa / Wbkt)

Channel Substrate (%): Boulder: — Cob: 10 Gra: 10 Snd: 50 Sil/Cla: 30

AHC: % of reach with altered hydraulic conveyance 100

ARV: % of flood prone area occupied by riparian vegetation 90

FI: % of floodplain isolated from overbank flow on right bank 100 and left bank 100

PSF: % of reach with perennialized flow nursery runoff 80

RCCR: % of reach area representing corridor breaks conduits to narrow 100

RRB: % if reach bounded laterally by culturally altered features 100

SR: % or reach with altered sediment regime probably an incised 100

channel prior to beginning of reach control based on the

Particle Size Classes: Boulder-large = 20+ in. Boulder-small = 10-20 in. Cobble = 2.5-1

Vegetation (Codes: D=dominant M=common P=percent C=channel F=floodplain S=sideslope T=terrace)

Trees	Vines	Shrubs	Herbs	Emergent Aquatics	Exotics	Grasses	Other
Plantanus racemosa	Vitis girdiana	Ambrosia	Conrya canadensis	Arenopsis californica	Arundo donax	Paspalum dilatatum	—
Populus trichocarpa	—	Artemisia californica	Epilobium	Cyperus microcephalus	Brassica sylvestris	Polygonum monspeliensis	—
Quercus agrifolia	—	Artemisia douglasiana	Heterotheca villosa	Eleocharis	Eucalyptus	Festucium vulgare	—
Quercus dumosa	—	Atriplex canescens	Frankenia grandifolia	Juncus dubius	—	—	—
Salix goodenii	—	Amorpha fruticosa	Onopordium	Panicum punctatum	—	—	—
Salix exigua	—	Baccharis pilularis	Phacelia	Rorippa nasturtium-aquaticum	—	—	—
Salix laevigata	—	Baccharis salicifolia	Pluchea sericea	Rumex	—	—	—
Salix lasiolepis	—	Baccharis sarothroides	Urtica dioica	Scirpus americanus	—	—	—
—	—	Eriogonum fasciculatum	—	Scirpus californicus	—	—	—
—	—	Hazardia squamosa	—	Scirpus robustus	—	—	—
—	—	Heterotheca grandiflora	—	Scirpus olneyi	—	—	—
—	—	Isocoma veneta	—	Typha latifolia	—	—	—
—	—	Lepidosapharum squamatum	—	Veronica anagallis-aquatica	—	—	—
—	—	Malosma laurina	—	Volula	—	—	—
—	—	Rosa californica	—	—	—	—	—
—	—	Rubus urinus	—	—	—	—	—
—	—	Toxicodendron radicans	—	—	—	—	—
—	—	Tribulus	—	—	—	—	—

Drawings / Cross Sections



US Army Corps
of Engineers

Engineer Research and Development Center

Example Data Collected for Reach Characteristics for MAWI

Size of Local Drainage Area	GIS
Valley Type (Rosgen)	Field
Valley Width (m)	Field/GIS
Downstream End Elevation	GIS
Valley Slope	GIS
Mainstem Channel Length	GIS
Drainage Density	Calculated
Bankful Width	Field
Natural Channel Substrate	Field
% of LULC contributing nutrients	GIS



Assessment Criteria

- **Criteria are the standards that can be used to make judgments or decisions concerning restoration, conservation and sustainable economic development**

- **For example:**

What is the condition of salmonid habitat?

What is the level of human disturbance?

Has water quality in a stream reach been comprised?

What is the extent and condition of riparian habitat?

Has the hydrologic regime in a stream reach been altered?

What is the erosion or landslide potential in a drainage basin?



Watershed Component	Assessment Criteria	Critical Issue Identified in POA
Uplands	Groundwater Condition	CI-7
	Land Use / Land Cover Condition	CI-9, CI-10, CI-11, CI-12, CI-13
	Upland Erosion / Surface Runoff Condition	CI-10, CI-11, CI-12, CI-13, CI-21, CI-28
	Point Source Condition	CI-22, CI-24, CI-27
	Forestry Practices Condition	CI-25
	Road Culvert Condition	CI-26
Riparian	Vegetation Condition	CI-1
	Woody Debris Condition	CI-1
	Exotic Vegetation Condition	CI-5
	Corridor Width and Continuity Condition	CI-1
Streams	Water Temperature Condition	CI-2, C-23
	Geomorphic Condition	CI-3
	Sediment / Substrate Condition	CI-4, CI-20
	Habitat Condition - General	CI-6
	Habitat Condition - Migration and Spawning	CI-8
	Surface Water Quantity Condition - General	CI-14, CI-15, CI-16, CI-17, CI-18
	Surface Water Quantity Condition - Salmonids	CI-19
	Surface Water Quality Condition	CI-20, CI-21, CI-24




Indicators





- **Indicators are measures designed to quickly and easily communicate information about the current condition of something of interest, and over time, about changes or trends in the condition**
- **For example:**
 - **Dow Jones Industrial Average or Body Mass Index**
 - **Land use / cover**
 - **Riparian canopy density and composition**
 - **Density of roads and road crossings**
 - **Percent of pools in a stream reach**
 - **Presence of invasive exotic species**
 - **Upland fauna diversity and abundance**
 - **Soil erodibility**



Baseline Watershed Assessment Tasks





FY 06 Product Development




Land Use Condition


- No support
- Very low
- Low
- Undetermined
- Moderate
- Strong
- Full support



Riparian Condition











Kleiss S. 00

Baseline Watershed Assessment Tasks








General Land Use Plan
Alternative
"Impact Area"




US Army Corps
of Engineers


Preferred Alternative
"Avoidance Area"



Engineer Research and Development Center




Incised Restoration Template




- ❖ Bankfull Width: 1.5 m
- ❖ Bankfull Depth: 0.15 m
- ❖ Flood Prone Width: 2.4 m
- ❖ First Terrace Width: 1.8 m
- ❖ Second Terrace Width: NA
- ❖ Height above Bankfull: 0.45 m
- ❖ Height Above Bankfull: NA



Change in Hydrologic Index Following Simulated Restoration




Change in Hydrologic Index / Level of Effort Following Simulated Restoration




LCA and MsCIP: Effects of Freshwater Diversions on Western MS Sound



CH3D boundary-fitted coordinates grid for Mississippi Sound




Subprovince 0.5 or the LA/MS Area



Land Building

Conceptual Elevation Model



- Distance from river or diversion
- Sediment Load
- Decrease in salinity
- Marsh “nourishment”



Subprovince 1




Figure C.8-9 Wetland area in Year 50 as a Result of Different Restoration Scenarios in Order of Increased Sediment Load

Habitat Use (White Shrimp)

V1 - percentage of km2 covered by marsh vegetation


V2 - mean salinity for summer (June, July, and August)

V3 - mean water temperature for summer (June, July, and August)

Suitability function for V1

$$SI_1 = \begin{cases} 0.036 \cdot V1 + 0.1 & \text{for } 0 < V1 \leq 25 \\ 1.0 & \text{for } 25 < V1 \leq 80 \\ 4.582 - 0.0448 \cdot V1 & \text{for } 80 < V1 \leq 100 \end{cases}$$


(White Shrimp)



Suitability function for V2

$$SI_2 = \begin{cases} V2 & \text{for } V2 \leq 1 \\ 1.0 & \text{for } 1 < V2 \leq 15 \\ 2.0 - 0.0667 \cdot V2 & \text{for } 15 < V2 < 30 \\ 0.0 & \text{for } V2 \geq 30 \end{cases}$$

(White Shrimp)



US Army Corps of Engineers



Figure C.9-1 Conceptual Model for the Habitat Switching Component

Scenario Comparisons

